

08.50

A00514191193+

4191193TEKGY G
17831 TEKSWED S

ZCZC
TBEVTN

*
QWQWRFL TTY
BG73
BT

SWL 509-054, JANUARY 16, 1985
TO: FACTORY SERVICE, TO WHO IT MAY CONCERN, 73-813
FROM: HAKAN HINTZE, TSTOKHM

THIS MAY HAVE BEEN CORRECTED ALREADY BUT I CAN'T FIND
ANYTHING IN MY MICROFICHE. IN 5CTIN/7CTIN C30 AND C32
ARE RATED 25V BUT THE VOLTAGE ACROSS THEM WHEN COLL.
VOLTAGE IS CCW IS CLOSE TO 30V.

REGARDS
HAKAN HINTZE
TEK SWEDEN

++++

QWQWETX
QWQWEOT
NNNN

*
4191193TEKGY G
17831 TEKSWED S
AEL7

17831 TEKSWED S

4191193TEKGY G

ZCZC TOD840 23.01.85 18.24 BIV681 656

.BIVT590

BD106

BE T590 1-23-85 TO HAKAN HINTZE, TSTOKHM
FROM JOHN EATON, BVTN SERV SUPT, 53-108/LA

RE: 5CTIN/7CTIN

C30 AND C32 ARE INDEED UNDER RATED FOR THAT CIRCUIT. I HAVE
REQUESTED THAT A MODIFICATION BE WRITTEN TO CURE THIS PROBLEM. WILL
LET YOU KNOW WHEN IT IS IN PLACE. THANKS FOR BRINGING THIS TO OUR
ATTENTION.

REGARDS,
JOHN

NNNN

17831 TEKSWED S

4191193TEKGY G

8

17831 TEKSWED S

4191193TEKGY G

ZCZC TOC454 08.05.85 00.28 BIV729 664

.BIVT556A

B2994

BE T556A 5-7-85 TO: HAKAN HINTZE, TSTOKHM
FROM: JOHN EATON, BEAVERTON SERVICE SUPPORT, 53-108/MF

RE: 5CTIN/7CTIN CAP RATING

THANKS FOR YOUR CONCERN, WE HAD OVERLOOKED THIS. A CORPORATE MOD IS NOW APPROVED TO CHANGE THE CAPS TO P/N 290-0817-00, THIS PART HAS A 63 VOLT RATING. THIS CHANGE SHOULD BE COMING OUT IN THE NEXT UPDATE OF MICROFICHE BUT CAN BE INSTALLED NOW. THANKS AGAIN FOR BRINGING THIS TO OUR ATTENTION.

REGARDS,
JOHN

NNNN8

17831 TEKSWED S

4191193TEKGY G